

CABINET REPORT CONCERNING PETITION TO COUNCIL TITLED – MARGATE STINK PORT
Annex 1 – Supporting Photographs



Margate – showing accretion of sediment within the Bay



Marine Terrace before 1887 – The tide reached the sea wall twice daily under normal conditions



Margate Harbour Sluice –Portland Stone and Brick sealing wall to culvert viewed from outer face of Stone Pier



Margate Harbour Sluice –open end of culvert viewed from inner face of Stone Pier