

Thanet District Council Tenant and Leaseholder Service Monthly Service Compliance Report

Meeting:	Monthly Monitoring Report to Service Management Team
Date:	19th April 2022
Monitoring Period	March 2022
Author:	Sally Osullivan (Tenant and Leaseholder Services Manager)
Summary:	This report covers health and safety compliance areas relating to Thanet District Council' housing stock, both for individual properties and for communal services and locations. The details of the current position with rates of compliance are detailed in appendix 3 The rate of progress is shown in annex 5. (graph)

Table of Contents

- 2 Lifts
- 4 Water
- 5 Fire Risk Assessments
- 8 Asbestos
- 10 Electrical
- 14 Gas
- 15 Glossary

Appendix 2: Metrics

Appendix 3: Supporting Graphs

<u>Lifts</u>

Compliance with written examination schemes for lift plant - LOLER (Lifting Operations and Lifting Equipment Regulations)	14 (100%)
Number of Entrapments in the month of March	O Entrapments this month (from Mears) 1 from Precision lifts (Kennedy)
Current Assets in domestic properties - lifts / hoist / stairlifts and changes in last month Defects identified by insurer	Hoists belong to KCC Stairlifts - 74 Non Compliant - 10 88.10% Compliant One installed at the end of February. Six LOLERs were completed in March, four were renewals which were already compliant. The other two had expired. The 10 expired The Compliance Team has tried to make contact. Where contact is made, the resident's details are passed to Zurich to call and make another appointment. The Compliance officer will be visiting each property where we have no contact, to establish contact details and to book an appointment. 1 x we are waiting for the lift to be removed from the property. Through floor lifts - 15 Non Compliant - 2 88.24% Compliant Both lifts are currently out of service, this has been passed to the contractors to complete.
inspection year to date	on passenger lifts from March 2021 to March 2022 Six New LOLERs were carried out in March 2022
Outstanding Defect A and Defect B risk actions as identified in insurers reports	Passenger lifts Defect A - 3 were reported in March - all completed

	Defect B - 22 - This has gone up from last month due to six LOLERs being completed in March (up from 18 in Feb)
	12 defect B's completed in March 16 Defect B's reported on LOLERS in March
	The team have regular meetings with the contractors for updates on the remedial works. This has improved communication and we have seen an improvement in receiving timely updates.
	Home aids (including stairlift and Through floor)
	Defect A Stairlift - 0 Through floor - 0
	Defect B Stairlift - 20 - This has gone up due six LOLERs being completed in March
	Through Floor - 4 Defect B x 4
RIDDOR Notices issued in relation to lift safety	None

Notes: Lift are now being Loaded onto True Compliance and reports are being set up, there has been a delay due to an issue reading the different certificates

Multiple breakdowns at Trove and Kennedy - we experienced multiple breakdowns following the refurbishment of the lifts in these 2 blocks. This has now been resolved

<u>Water</u>

Total Properties - Domestic Communal Other	Domestic - 3054 Communal - 274 Garages - 354 Garages block - 34 Commercial - 3
Properties on the Legionella Risk Assessment (LRA) Program	28
Properties with a valid in date LRA as a number and overall percentage	28 100% Compliant
Properties which are due to be inspected and tested within the next 30 days - this is the early warning system	0
Number of follow up works / actions arising from risk assessments and inspections - completed / in time and overdue	High Risk - 1 (from 7 in Feb) Medium - 16 (From 25 in Feb) Low - 0
Current Position	All outstanding are within residents properties. We have experienced access issues, so we are confirming appointments with the residents before the date. Over the last month this has allowed us to close down 28 actions in February and 15 in March. We are also dedicating time to go out and visit the residents where access has been hard and this has contributed to the success. 9 Medium actions are legacy actions where we cannot access properties
	The final high risk is not a legionella risk and is actually for the potable water (drinking water). Awaiting date from contractor to complete.
Corrective Action required	Legal have confirmed we can use a forced entry process to any actions where it puts risk on the whole block. This currently does not cover the outstanding actions.
Progress with completion of follow up works - number of actions completed / in time / overdue	High Risk Actions - 1 outstanding 1 overdue

Medium Risk Actions - 16 outstanding 16 Overdue

Notes: Legionella Risk Assessments are currently being mapped onto True Compliance

Fire Risk Assessment

	,
Properties - Split by Communal blocks and 'other' properties	Residential Blocks: 274 (One of these is The Leys which is leasehold) Other: 4 - 2 are communal halls, 1 is a complete leaseholder block which TDC has no responsibility for. One is the Harbour Towers Car park.
Properties on the FRA Programme	167 (2 of these are Community Halls and one communal car park)
Properties not on the FRA Programme	111
Properties with a valid in date FRA. This is the level of compliance as a number and overall percentage	167 in date 100%
Properties due for FRA within 90 days. This is the early warning system	3 FRAs
Follow up works - total number of actions (by priority) raised in period completed and outstanding - and time outstanding	No FRA's were due in March, therefore no actions added Total actions = 219* *187 planned works actions all together 86 planned works actions are being addressed immediately 101 of the planned works actions are programmed over the next 5 years. These actions have now been moved off the day to day actions and will be counted separately.
Narrative, including • Current Position	Total actions = 219 Overdue - 75 Current - 144 4 actions outstanding from FRA's carried out by EKH (prior Oct 2020)

Corrective Action Required

- 1 is with the planned team they now have quotes in and planning the budgets
 1 is with the compliance team, this is a fire door inspection, one of the two courses have now gone ahead and ipads are on order.
 2 are with the repairs team for new doors. There is delay in manufacturing so they are awaiting for the materials to be delivered before fitting.
- 53 Actions outstanding prior to Oct 21.

From Oct 21 to present day, we have 165 actions

- Anticipated impact of corrective action
- Progress with completion of follow up works

Housing - closed out **29** actions in March Repairs- closed out **28** action in March Compliance- closed out **51** actions in March Planned works-closed out **0** actions in February **Total 108**

Total of 44 actions became overdue in March.

Total Overdue 144:

45 overdue with repairs

8 have appointments in April and May 20 are waiting for new door sets but there is a delay at the manufacturer, these are expected in May but only estimated time - these actions included more than one door in a block and some have been carried out but action left open as other doors are needed.

11 No access issues, these actions included more than one door in a block and some have been carried out but action left open as other doors are needed.

1 is a leaseholder who has had a new front door put in themselves and states it is fire rated. The homeownership team is working with the leaseholder to confirm the paperwork. 2 action relates to several letterboxes in one

2 action relates to several letterboxes in one block to be upgraded, the TDC residents have been completed but the leaseholders still need completing.

1 Door to be completed on void

1 resident has bed bug issues and refusing access however this is a front door and engineer is happy to complete work, letter has been sent to resident

1 possible abandoned property, NTQ served, ends 16th May

A Lot of the repairs actions relate to more than

one property (doors or letterboxes in one block) most of which have been installed however there is the last one or two in the block that require completing. The action will be closed once these are completed.

Weekly meetings with Mears to ensure open cases are progressed

22 overdue with Compliance

15 are loft inspections to be carried out within residents flats. These have had one failed visit. Waiting contractor to rebook.

1 is waiting for a new alarm, the quote is in from the contractors TDC are getting drawings, planning permission and to run through KFRS 1 the new alarm has started but no access has happened in some properties, now on third no access.

1 is for new bin store which is being put on the planned programme when the bin store programme has been set

1 Planning permission is required

1 is an elderly leaseholder who was difficult to contact, confirmed appointment now in for May 2 waiting on fire door inspections, the first fire door course has gone ahead, waiting on Ipads to be able to complete inspection, form also needs to be agreed.

38 overdue with Planned All have quotes, the budgets are being agreed.

39 overdue with Housing

Tort notices are on going, compliance to work closer with housing to ensure the FRA photos are sent to housing to confirm what items are within the communal area.

We are finding the items are being removed and either put back or other items put within the communal areas.

Additional, including;

Compliance with fire safety equipment, systems and installation servicing and maintenance programmes.

Tower blocks:

Staner Court

New fire alarms system and AOVs now complete .

Brunswick Court

New fire alarm system and AOV upgrade is now complete

Harbour Towers

New fire alarm system and AOV upgrade is now

	complete
	Fire Alarms - 22 compliant 9 - Non Compliant
	Four are waiting for new systems to be installed as the old EMS panel is in place and now parts are obsolete. Three - Towers blocks are planned works and the programme continued in March at Invicta House. This is mitigated with the waking watch on site. One - Royal Creas is part of a project One - Waiting for quote
	AOV - 100%
	Emergency Lighting - 94.96% The 6 non-compliant have been completed. We are just waiting for the certs from the contractors.
	Fire Extinguishers - 100%
 Recording and reporting on property fires to identify trends and target awareness campaigns. 	No fires were reported in March.

Notes: There was a delay in mapping the FRAs and the issue had to be pasted back to the developer. This has now been rectified and FRAs started to be uploaded on TC at the end of February

<u>Asbestos</u>

Total number of properties split by non domestic properties (communal blocks) and 'other' properties	Domestic - 3054 Communal - 274 Community building - 2 Garage blocks - 34
Properties on the asbestos management / re-inspection programme	Domestic - 2979 Communal - 117 Community buildings - 2 Communal Garage blocks - 34
Properties with a valid in date survey / re-inspection. This is the level of compliance as a number and percentage	Domestic - 1638 54.98% 36 Surveys completed in March Communal - 117 100%

	Community buildings - 116 98.31%
	Garages - 1 - 2.94%
Properties due to be surveyed / re-inspected in the next 90 days. This is the early warning system.	Communal - 0 Next surveys aren't due until September. The Compliance Manager and contractor are in discussion to spread this more evenly over the year and there is a spike at the end of the year.
The number of follow up works / actions arising from surveys and the numbers 'completed,' 'in time' and 'overdue.'	Works domestic: from 19 in February to 15 in March 10 - v low 2 - low 3 - Med All legacy actions now complete Communal - Two outstanding, both are booked in with the contractors to be encapsulated
Narrative including: • Current Position	The one legacy action that was outstanding has now been completed and there are no more legacy actions.
Corrective action required	 To continue to complete the domestic surveys and all remedial works. To spread the communal programme more evenly over the year so there isn't such a spike at the end of the year. To go through the surveys to see where we can remove some asbestos so we will be able to remove it from the inspection programme.
Anticipated impact of corrective action	 To get to 100% on domestic properties. There will not be a spike and rush to complete the communal ones at the end of year which will allow us more time to go through the remedial works and quality of survey. This will lower the amount of re inspection surveys we carry out, saving us time and money.

 Progress with completion of follow up works - number of actions 'completed,' 'in time' and overdue. 	0 in March, all in date
---	-------------------------

Asbestos Notes: Asbestos will be the final to go on True Compliance.

Electrical

	
Total number of properties split by domestic, communal blocks and other	Domestic - 3054 Communal - 274 Commercial buildings - 2 Garages block - 34
Properties on the electrical inspection and testing programme	Domestic - 3054 Communal - 164 Commercial building - 2 Garage blocks - 1
Properties with a valid in date EICR (In line with 10 year inspection period). This is level of compliance expressed as a number and a percentage	129 properties total with a 10 year EICR 123 compliant with a 10 year EICR 95.34% compliance Communal 1 properties with 10 year EICR Domestic 128 properties with 10 year EICR
Properties with an expired and out of date EICR (In line with 10 year inspection period). This is level of non compliance expressed as a number and a percentage	2.28% Domestic - 1 of which have expired and forced entries have now been authorised to go ahead. Letters to be sent out to start process 3 of which have expired are hoarders and with the housing team, referred at the end of March. 1 non compliant has access issue, it has had its three carded, the compliance team have attempted to make contact but no answer. This property has also been lettered by the contractor and the compliance team. Next step is for the compliance team to visit the property and ask housing for assistance. Communal - 1 properties with non compliant 10 year EICR (property previously showing on our list as having no communal supply, came to light

	when searching back through old spreadsheets & raised by the leaseholder who highlighted that she is paying for communal electrics) We completed an unsatisfactory cert for this on 01 February, this is down to it being connected within flat 1s consumer unit. We are getting this separated. The work has now been authorised with our contractor and UKPN and works are to begin in May.
Properties with a valid in date EICR (In line with 5 year inspection period). This is level of compliance expressed as a number and a percentage	3,087 with a 5 year EICR (comm & dom) 2,793 Compliant with a 5 year EICR (Com & Dom) 90.41% Compliant Communal 161 Blocks with a valid 5 year EICR Domestic 2,631 properties with a valid 5 year EICR Garage - 1 garage with a valid 5 year ECIR Community Buildings - 2 Buildings with a valid 5 year ECIR
Properties with an expired and out of date EICR (In line with 5 year inspection period). This is level of non compliance expressed as a number and a percentage	22 - Certificates not found - these are being counted as a priority for an EICR (down from 54 last month) One is a completed waiting cert. One is a new building which we are awaiting the cert. 6 with future appointments, 8 with three carded appointments, 4 are ones we have spoken to the resident and there are underlying issues due to disabilities and covid reasons. 172 - Non compliant, unsatisfactory certs (down from 385 last month) 103 came back from NRT 20 are newly unsatisfactory certs, needing remedial works. 46 have had three letters, 4 have had 2 letters, 33 have had at least one letter from contractor NRT only. 69 with Mears, 13 Mears have future appointments 12 have had three visits, 12 have had two visits and 16 have had at least one visit

26 of the non compliant have been visited by the Compliance Team in March.

33 Non Compliant have appointments booked for remedial works / programmed in for April.

7 Non compliant we have been told by the contractor have been completed but are awaiting cert - which we have been chasing.

These figures will not tally up to 172 as some of the addresses will fall into a few of the breakdowns due to hitting certain criteria so will be counted twice.

- **35** Expired (down from 71 last month) All have future appointment dates 13 have had 3 or more carded dates
- **6** Void One unsatisfactory cert, remedials are being completed on void. One expired but being completed on void
- **19** Are with housing officers which are a mixture of social issues, going through a process. Compliance team and housing are working together to get through these, these are long term issues. However one has an appointment in March.
- **40** access issues (down from 63 last month)All have had three or more letters/ carded visits, one has a future appointment and another has a three day rewire booked in for April.

All of the non compliant/ access issues will be visited/revisited in May by the compliance team and appointments will be made at the door between resident and contractor or a compliance letter will be posted through the door. This was completed in a previous month and out of 107 visits where 42 appointments were booked.

Properties which are due to be inspected within next 30 days - this is the early warning system

TDC have instructed the contractors to complete the unknowns, overdues and then 10 year certs this will bring us in line with regulations.

27 due in 90 days

These have all been sent to the contractor to be planned in.

Weekly meetings are still happening with Mears to update and go through any concerns or issues so the compliance team can address.

Narrative including:

- Current Position
- Corrective action required
- Anticipated impact of corrective action
- Progress with completion of follow up works

NRT had 535 over all. NRT has now finished helping with EICR due to budget.

NRT completed 378 compliant EICRs

22 requires remedial works, as the work has now been completed full EICR is now required as one electrician will not sign off another engineer's work.

135 now handed back to Mears, All of which have been lettered by NRT and the compliance team, the compliance team letters were hand delivered.

Ball Contractor - had 30 address to which they completed 10 Handed back 20

PJC - 30 overall, Completed 4 PJC, we are waiting on an update to see if PJC will be continuing.

CEAS - 40 over all 23 Completed Waiting for an update on the rest of the jobs.

TDC compliance team are calling ahead to confirm the residents appointments.

TDC Compliance officer visited 107 properties to make appointments with the residents and contractors on the doorstep. With the resident who weren't in, a letter was dropped.

This process will be repeated with all outstanding EICRs as this proved to be very beneficial with 42 appointments booked on the doorstep.

Notes: TDC Compliance team have now loaded the certs on True Compliance and are working on some customisation for TDC.

<u>Gas</u>

Total number of properties split by domestic, communal blocks and 'other'	Domestic - 3054 Communal - 274 Community building - 4 Garages block - 34
Properties on the gas / heating programme	2607
Properties with a valid in date LGSR certification. This is the level of compliance expressed as a figure and a percentage	2607 100% Complaint
Properties due to be serviced in the next 30 days. This is the early warning system	18 - All have booked appointments and the forced entry process has started.
The number of follow up works / actions arising from any tests / inspections and the numbers completed, in time and overdue	Our new system will provide this information, all certs have been loaded and contractors are now loading the portal. Next step is the remedial work and train contractors on this
	There is a lot of work to be done first to close down ones where there aren't actual works completing

Notes: True Compliance is now live for the Gas Stream and Gas Call is uploading the LGSRs directly onto the system.

Glossary

True Compliance - a compliance database, recently procured to hold all compliance information.

LOLER - Lifting Operations and Lifting Equipment Regulations. This is the inspection that lifts must have twice per year to prove they are safe and compliant. Actions that come out of this inspection fall into the following categories:

- A defect this is a serious risk to health and safety. The action must be completed there and then or the lift needs to be decommissioned
- <u>B defect</u> is a low or medium risk to health and safety. This must be completed before the next LOLER inspection in 6 months,

Entrapment - when a person or persons becomes trapped in a passenger lift. There is a call point in the lift for them to call for help.

Legionella Risk Assessment (LRA) - a programme of inspections required to ensure the risk of stored water supplied to residents (i.e. properties with shared water tanks) is low risk for harbouring legionella bacteria.

Fire Risk Assessment (FRA) - a programme of inspections required on flatted blocks that have a shared internal communal space. The frequency is between 1 - 3 years depending on the risk rating of the block.

EICR - Electrical Installation Condition Report - carried out once every 5 years on communal areas with an electrical supply on all tenanted properties. We used to be able to obtain 10 year certificates until the regulations changed on 1 April 2021.

LGSR - Landlord Gas Safety record - carried out annually